

SMART SOUNDBAR 10 S2

Release Datum: 12.02.2024

Neue Firmware Revision:

WiFi	15493
Chromecast built-in	1.52.272222
MCU Host	4.290
STS wireless	1.17
DSP Audio	2.70
OSD Fonts	1.20

Alte Firmware Revision:

WiFi	15379
Chromecast built-in	1.52.272222
MCU Host	4.285
STS wireless	1.17
DSP Audio	2.70
OSD Fonts	1.20

Neue Funktionen und Änderungen:

- Soundbar 10 für die Steuerung per Canton Smart App optimiert.
- Möglichkeit zum Herunterladen von Log Dateien im Webinterface eingefügt.

Fehlerbehebung:

- Allgemeine Stabilitätsverbesserungen.

Tipp:

Sollte Ihr Gerät nach dem update ein unerwartetes Verhalten aufweisen, führen Sie bitte eine OTA Wiederherstellung durch. Diese Funktion finden Sie im Menü unter folgenden Punkten:
Systemeinstellung --> Werkseinstellung --> OTA Wiederherstellung

SMART SOUNDBAR 10 S2

Release Date: 12.02.2024

New firmware revision:

WiFi	15493
Chromecast built-in	1.52.272222
MCU Host	4.290
STS wireless	1.17
DSP Audio	2.70
OSD Fonts	1.20

Old firmware revision:

WiFi	15379
Chromecast built-in	1.52.272222
MCU Host	4.285
STS wireless	1.17
DSP Audio	2.70
OSD Fonts	1.20

New functions and changes:

- Soundbar 10 is now optimised for being controlled via the Canton Smart App.
- Possibility to download log files added to the web interface.

Bug fixes:

- General stability improvements.

Tip:

If your device shows an unexpected behaviour after the update, please execute an OTA recover. This function can be found in the menu under system setup --> factory reset --> OTA recover.