

**Release Datum:** 12.02.2024

### Neue Firmware Revision:

WiFi	15493
Chromecast built-in	1.52.272222
MCU Host	2.290
STS wireless	1.17
DSP Audio	2.70
OSD Fonts	1.20

### Alte Firmware Revision:

WiFi	15385
Chromecast built-in	1.52.272222
MCU Host	2.287
STS wireless	1.17
DSP Audio	2.70
OSD Fonts	1.20

### Neue Funktionen und Änderungen:

- Soundbar 10 für die Steuerung per Canton Smart App vorbereitet

### Fehlerbehebung:

- Allgemeine Stabilitätsverbesserungen

Tipp: Sollte Ihr Gerät nach dem update ein unerwartetes Verhalten aufweisen, führen Sie bitte eine OTA Wiederherstellung durch. Diese Funktion finden Sie im Menü unter Systemeinstellung/Werkseinstellung/OTA Wiederherstellung

**Release Date:** 12.02.2024

### New firmware revision:

WiFi	15493
Chromecast built-in	1.52.272222
MCU Host	2.290
STS wireless	1.17
DSP Audio	2.70
OSD Fonts	1.20

### Old firmware revision:

WiFi	15385
Chromecast built-in	1.52.272222
MCU Host	2.287
STS wireless	1.17
DSP Audio	2.70
OSD Fonts	1.20

### New functions and changes:

- Soundbar 10 is now optimised for being controlled via the Canton Smart App

### Bug fixes:

- General stability improvements

Tip: If your device shows an unexpected behaviour after the update, please execute an OTA recover. This function can be found in the menu under system setup/ factory reset/ OTA recover.